


Nailed Only Sub-Floor

Spruce-Pine-Fir
5/8 Sub-floor
40/10 Loading




Glued and Nailed Sub-Floor

Spruce-Pine-Fir
5/8 Sub-floor
40/10 Loading

Hemlock Fir
5/8 Sub-floor
40/10 Loading

Douglas Fir
5/8 Sub-floor
40/10 Loading



Notes:

1. All floors are strapped or have ceiling applied
2. NBCC Code Floors contain conventional bridging
3. All lumber is #2 and better, as per NLGA

FEET